



Nonfunctional sashes have been packed with tissue to reduce drafts



Sashes, sills, and putty are beyond repair



Sashes, sills, and box frames have no structural integrity



Many of the glass panes are uniformly transparent and not original



There are signs of previous repairs to sills, stiles, and meeting rails



Box frames are rotten and weights have seized

NOTE:
 1) © This drawing is the property of Crayon Architects and should not be copied, reproduced or used for the purpose other than which it has been prepared.
 2) All dimensions to be checked on site.
 3) Any discrepancies found in the plans, dimensions, existing conditions or any apparent error to be pointed out to the architect prior to commencement of work.

NOTE: Windows and doors not shown to remain as existing

All photographs taken by the owner

Rev Amendments Date Drawn By



Office 12, 25 The Crescent, Plymouth, PL1 3AD
 01752 242073 www.crayonarchitecture.co.uk

client	Mr & Mrs Jenkins	
job title	Replacement Windows Woodside Cottage, 1 Woodside, Plymouth, PL4 8QE	
drawing name	Photographs 4	
drawing status	LISTED BUILDING APPLICATION	
drawn by	checked by	date
DA	AA	Oct '23
drawing number	scale	
2309_LB14	NTS@A3	