



Scale: 1:5,000




Legend

Defences

- Barrier Beach
- Beach
- Bridge Abutment
- Cliff
- Demountable Defence
- Dunes
- Embankment
- Engineered High Ground
- Flood Gate
- Natural High Ground
- Promenade
- Quay
- Spillway
- Wall

This data has been extracted from the Asset Information Management System (AIMS OM) which was created to draw various data sources into one database and has been populated with information of varying quality.



Product 4 - AIMS Information

323163-WX

Date:

29/08/2023

Map Ref	Asset ID	Asset Type	Right or left bank	Asset Description	Approx length (m)	Actual fluvial downstream crest level (mAOD)	Actual fluvial downstream crest level accuracy	Actual fluvial upstream crest level (mAOD)	Actual fluvial upstream crest level accuracy	Actual fluvial coastal crest level (mAOD)	Actual fluvial coastal crest level accuracy	NGR	Most recent inspection	Overall condition
4	131980	Natural High Ground	Left	DNR	204.57	94.43	4 - +/- 0.75m or more vertical accuracy	95.19	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73638192	07/08/2023	3 - Fair
18	2528	Natural High Ground	Left	DNR	148.81	91.51	4 - +/- 0.75m or more vertical accuracy	92.50	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST72848233	07/08/2023	3 - Fair
19	2529	Natural High Ground	Left	DNR	271.01	92.35	4 - +/- 0.75m or more vertical accuracy	91.74	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73208256	07/08/2023	3 - Fair
37	41338	Natural High Ground	Right	DNR	21.56	91.24	4 - +/- 0.75m or more vertical accuracy	91.45	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST72868235	07/08/2023	3 - Fair
38	41339	Natural High Ground	Right	DNR	30.45	90.72	4 - +/- 0.75m or more vertical accuracy	90.74	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73318264	07/08/2023	3 - Fair
45	5361	Natural High Ground	Left	DNR	34.54	91.74	4 - +/- 0.75m or more vertical accuracy	91.72	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73328263	07/08/2023	3 - Fair
46	5362	Natural High Ground	Left	DNR	756.60	92.17	4 - +/- 0.75m or more vertical accuracy	94.43	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73478241	07/08/2023	4 - Poor
48	5364	Natural High Ground	Right	DNR	275.75	91.14	4 - +/- 0.75m or more vertical accuracy	92.09	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73078246	07/08/2023	3 - Fair
49	5365	Natural High Ground	Right	DNR	266.35	92.09	4 - +/- 0.75m or more vertical accuracy	90.72	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73208258	07/08/2023	3 - Fair
50	5366	Natural High Ground	Right	DNR	981.12	91.74	4 - +/- 0.75m or more vertical accuracy	94.60	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73568227	07/08/2023	3 - Fair
51	78772	Natural High Ground	Right	DNR	104.52	91.55	4 - +/- 0.75m or more vertical accuracy	91.66	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST72818233	07/08/2023	3 - Fair
53	90730	Natural High Ground	Left	DNR	251.76	92.50	4 - +/- 0.75m or more vertical accuracy	91.44	4 - +/- 0.75m or more vertical accuracy	DNR	DNR	ST73098245	07/08/2023	3 - Fair

Notes

- * Overall Condition has been taken from the most recent inspection
- * Inspections are of a purely visual nature and do not necessarily reflect the true condition of the asset
- * Condition: 1 = very good, Condition 2 = good, Condition 3 = fair, Condition 4 = poor, Condition 5 = very poor
- * Crest level accuracy: 1 = ± 0.01 to 0.05m, 2 = ± 0.05 to 0.15m, 3 = ± 0.15 to 0.75m, 4 = ± 0.75 or greater
- * DNR = data not recorded