


Proposed east elevation




Proposed north elevation

PROPOSED POOL HOUSE ELEVATIONS





Proposed west elevation



Proposed south elevation

- Existing red brick in Flemish bond internally insulated with breathable insulation.
- Existing pantiles retained.
- Existing stable doors with new glazed doors inserted into reveal to create thermal line.

 Proposed aluminium rainwater goods; deep flow half round with traditional style downpipes
- Brickwork repair; brickwork to be locally repaired where needed in matching brick and mortar.

- Photovoltaic panels (shown indicatively, sizing TBC). Conservation rooflight. Proposed reclaimed clay pantiles to closely match existing
- 10. Existing garden wall retained
- 11. Existing bargeboards and eaves fascias replaced to match existing, or redecorated as necessary
- Proposed window/glazed slot behind existing opening
 Proposed glazed painted timber French doors
 Existing timber stable doors to be restored. New glazed doors installed within internal reveal to form thermal line
 Proposed window.
 External terrace/hard landscaping.

