



Proposed south elevation




Proposed north elevation

PROPOSED GARAGE ELEVATIONS





Proposed east elevation



Proposed west elevation

- Proposed red brick in Flemish bond.
- $\stackrel{\cdot}{\text{Glazed black pantiles; tiles and ridge tiles to be carefully removed and reinstated following insulation and struc}$ Proposed painted timber door.
- Proposed aluminium rainwater goods; deep flow half round with traditional style downpipes.
- Proposed painted lime render.
- Proposed painted lime render.
 Stable partitions; existing retained and refurbished.
 Brickwork repair; brickwork to be repaired in matching brick and mortar.
 Proposed glazing and sliding doors; hardwood frame internally and hardwood capping externally
 Parapet capping to be removed and reinstated following re-roofing and flashing works.
 Photovoltaic panels (shown indicatively, sizing TBC).
 Link roof; single ply membrane with sedum blanket.
 Frameless glass "slot".
 Conservation rooflight.
 Glazed black pantiles.
 Vertical timber cladding and matching garage doors.
 Air source heat pump (indicative; size and specification TBC).
 Proposed painted hardwood sash window
 Existing brick pier

- Freposed water store (for kitchen garden). Fed from roof of garage.

