

East Elevation

- Proposed red brick in Flemish bond.

 Glazed black pantiles; tiles and ridge tiles to be carefully removed and reinstated following insulation and struc
- Proposed painted timber door.
- Proposed painted lime render.
- Stable partitions; existing retained and refurbished.

 Brickwork repair; brickwork to be repaired in matching brick and mortar.

 Proposed glazing and sliding doors; hardwood frame internally and hardwood capping externally
- Parapet capping to be removed and reinstated following re-roofing and flashing works.
- 10. Photovoltaic panels (shown indicatively, sizing TBC).
- Link roof; single ply membrane with sedum blanket.
 Frameless glass "slot".
- 13. Conservation rooflight.
- 14. Glazed black pantiles.
- 15. Vertical timber cladding and matching garage doors.
 16. Air source heat pump (indicative; size and specification TBC).
 17. Proposed painted hardwood sash window

18. Proposed hardwood window behind existing timber door NOTE: Existing windows to be thermally upgraded with either secondary glazing or slimline double glazed

PROPOSED EAST ELEVATION LINE





