



PHOTO 1:

WALL OUT OF ALIGNMENT
OPEN MORTAR JOINTS.
BRICK FACES DAMAGED THROUGH
FROST ACTION.



PHOTO 2:



PHOTO 3!



PHOTO 4:



PHOTO 5:



PHOTO 6:



PHOTO 7:



PHOTO 8



APPROX 14 LINEAR METRES OF EXISTING FACING BRICK WALL TO BE TAKEN
DOWN; SALVAGED BRICKS CLEANED OFF & REUSED TOGETHER WITH LIME
MORTAR MIX.



PHOTO 9

CHURCH OF ST CHARLES BORROMEIO,
HAMPTON ROAD,
HAMPTON ON THE HILL,
WARWICK,
CV35 8QR.