





The roof of the extension is currently overgrown with biological materials









The roof of the extension is currently overgrown with biological materials









Front (south) Elevation with 20th Century garage doors and pass door added



Rear (north) elevation is partially hidden, acting as a retaining wall to the adjacent ground







PROPOSED EXTENSION - PHOTOGRAPHIC RECORD OF EXISTING EXTENSION



Rear (north) elevation is partially hidden, acting as a retaining wall to the adjacent ground







PROPOSED EXTENSION - PHOTOGRAPHIC RECORD OF EXISTING EXTENSION



Rear (north) elevation is partially hidden, acting as a retaining wall to the adjacent ground









Left hand (west) elevation which has been covered in cement harling









Left hand (west) elevation which has been covered in cement harling









The cement harling is failing over parts of the extension (and main building)







PROPOSED EXTENSION - PHOTOGRAPHIC RECORD OF EXISTING EXTENSION



Cement harling, modern garage doors, modern concrete cope and light fitting to south elevation









South and west elevations showing the garage door, modern access door, cement render and concrete cope









The south elevation of the extension connects back to the northernmost jerkin headed gable









The extension shown in a wider context against main house

