Appendix TFT Photographs



Photo 1: General View front elevation.



Photo 2: Rear elevation.



Photo 3: Rear elevation high level.



Photo 4: Roof level plant area.




Photo 5: Spalling to concrete frame.



Photo 6: General roof area.



Photo 7: Asphalt covering to flat roof area.



Photo 8: Spalling stone to the read elevation.



Photo 9: Loose / Cracked pointing to stone.



Photo 10: Splits / cracks to decoration to front elevation. Paint runs visible.




Photo 11: Crack to joint between 15 Regent Street and adjacent property.



Photo 12: Flank elevation