

Appendix 1



Timber front door beyond repair. To be replaced on a like for like basis in timber reusing all existing door furniture.



Proposed pitched roof veranda over backdoor and French doors in area shown. Oak framed, single oak post at outer corner, glass roof, lead flashings. Lead box gutter to replace existing plastic gutter above backdoor discharging to cast collector and downpipe replacing existing plastic items