



General Roof Repairs

Render removed and Norfolk Red Brick underneath in good condition. Rerender proposed for black band to bottom as brickwork not in such good condition as cement render damaged and sat wet for decades. Main facade to be returned to original brick finish.