



Replacement windows

- A - Chimney to be rebuilt as in very poor condition and in danger of collapsing
- B - General roof repairs
- C - Render to be removed, brickwork repaired around door and condition assessed to allow for red brick underneath to remain
- D - Render removed, bitumen paint beneath to be removed and elevation to be painted in neutral colour. Windows to be replaced with wooden sash with glazing bars
- E - Render removed and redbrick and flint to be retained as in good condition.