

South-west external wall to be repaired, insulated, rendered, and then painted white to match the rest of the existing house. Wall highlighted in red below.

