


Existing window
elevation, dating from
1990's
East wall, Hall.



Scale 1:25

Wooden window sill
Modern blockwork infill

Water level during winter months

Wooden floor

Concrete subfloor (?1970's)