

Rear of club, east facing, four windows on left of the building to be replaced. Two upper floor and two ground floor (one set back).



Two upper floor and  
two ground floor (one  
set back).