



Site photo showing patio door installation



Site photo showing flat roof window and Velux roof window.



Part West elevation as proposed


Unforeseen works

It is not always possible to identify all elements of construction of an existing building without carrying out extensive disruptive surveys at an early stage. The client should make allowance within their contingency for any costs associated with unforeseen works uncovered as the works progress.

CDM (Construction - Design and Management) 2015

In order to avoid forseeable risks The Principal Designer has eliminated hazards where reasonably practicable at the design phase. Where forseeable hazards could not be designed out and in order to reduce the risk associated with those that remain, the following hazards have been identified:

1. 2.



© Copyright of Architectural Building & design Consultants Ltd

Drawings to be read & fully understood before work commences. **IF IN DOUBT ASK.** Use figured dimensions only.

All dimensions, spot levels and drainage positions to be checked on site by Contractor prior to construction. Any discrepancies to be reported back to ABC Ltd

0 0.5m 1m 1.5m 2m 2.5m 5m SCALE BAR 1-50



15 Westgate North Berwick
Plans/Elevations as proposed

Architectural Building & Design Consultants Ltd

18a Rothesay Place, Edinburgh EH3 7SQ

O131 510 8555 Edinburgh o1368 908 222 Dunbar

Begin Consultants Ltd

Emma Hargreaves

Project ref. REF No.583

O2

Planning.

Scale Print Date

1:50 A1

O3/11/23

Sjw XXX