

Rectory Cottage. DC/22/04668
Condition 10 - Render Mix and Finish.

Following research regarding Lime render and with confirmation from the subcontractor, the render is as follows;

“The scratch coat is a mix of non-hydraulic lime, hemp shiv, chalk and fibre, with an added pozzolan (metakaolin), approximately 4:1.

The top coat is sand and fibre, a non-hydraulic lime, chalk. Ratios approximately, 2:1:1.

We make up our own plasters because it gives us the flexibility to match the specification to the specific context.”