

Site Investigation Report

Auger Ref:

143562.2.BSI



Job Information

Client	Crawford's
Client ref	SU2204195
Visit date	15/02/2023
Report date	08/03/2023

Job Summary

✓ 1 trial hole undertaken. [Read more.](#)



INVESTORS IN PEOPLE®
We invest in people Gold

Job Information

Overview

Brief

Auger were commissioned by Crawford's to undertake a site investigation within the area of concern (AOC) at the property.

Findings

Trial Hole Findings

TH2 was completed in the proposed location. The footing was revealed and in situ testing was done down to 3m.

Photographs

Trial Hole 1

Fig 1.1: Trial Hole 2 Location



Fig 1.2: Trial Hole 2 Footing



Site Photos

Fig 2.1: Trial Hole Open




Fig 2.2: Footing



Fig 2.3: Rubble within Hole





FRONT OF PROPERTY

This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND			
	= Manhole (MH)		= Blockage / Collapse
	= Inspection Chamber (IC)		= Soil Vent Pipe (SVP) / WC
	= Inspection Point (IP)		= Combined Waste Gully (CWG) / Foul Waste Gully (FWG)
	= Rainwater Gully (RFG)		= Rainwater Pipe (RWP)
	= Lines not camera surveyed		= Lines camera surveyed
	= Assumed water mains feed		= Walls
	= Fences		= Building Outline
	= Trial hole		= Borehole
	= Direction of flow		= Gate / Door
	= Shrubs / Bush		= Hedge
	= Tree		= Steps



Trial Hole Log No.2

Location: Rear Rh corner

Job Ref:
143562.2.BSI

Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0	<p>150mm</p> <p>Ground Level</p> <p>Stone</p> <p>Flagstones</p> <p>Blockwork</p> <p>Concrete</p>					
0.5						
1.0						
1.5						
2.0			150kpa			
2.5		Dry hard mottled CLAY	150kpa			
3.0		TRIAL HOLE TERMINATED	150kpa 150kpa			