

Photographic Schedule

Site: 15 High Street, Chipping Sodbury, South Glos, BS37 6BA



Photograph 01 – View of the principal southern elevation.



Photograph 02 – View of the bay window, door and sash window to which the application relates.



Photograph 03 – Internal view of the bay window and door to which this application relates.



Photograph 04 – Internal view of the bay window plinth wall. Note the damp issues.



Photograph 05 – Typical example of poor condition of bay window frame.



Photograph 06 – Typical internal view of bay window. Again, note the damp issues and poor condition of softwood joinery.



Photograph 07 – Typical internal view of the door to which this application relates. Note the state of disrepair.



Photograph 08 – Internal view of first floor sash window to which this application relates.



Photograph 09 – Internal view of sash window. Note the poor condition of the frame and glazing bars.



Photograph 10 – Typical internal view of sash window. Note the poor condition of the frame.