

EXISTING BARN STABILITY

The existing barn which is to be converted is a brick built building with a concrete pantile roof. The photographs below shows the building is in an exceptionally good condition and has no signs of any structural defects. All the brickwork, the roof coverings and the internal roof structure can all be seen to be in a very good structural condition. Although a detailed structural report and design will be required prior to the conversion of the barn it is not felt a structural report is required to prove the currently stability of the building as this can be clearly seen.







