

No major alterations are being undertaken. The internal layout will remain the same. The existing fittings are being upgraded.

The staircase will remain in situ and will not move. Paintwork will be updated. The office doors will be replaced with domestic doors of the era. Any office partitioning will be removed to bring the rooms back to original.

Some external maintenance needs to be undertaken ie: render repair, painting of windows and roof repair. Scaffolding will be required.