

Existing pair of narrow double doors with rebated meeting stile, requires secondary leaf to be bolted for primary leaf to engage latch.

Clear opening width through one leaf restricted to approx. 700mm.



Raised door threshold bowing and riser piece decayed. Door threshold to be lowered down to original step level flush with new floor level.



Existing fluted lining to reabted frame.



Original gunstock stile doors appear to have has glazed sashes inserted into the original glazing rebate.



Mismatched and poorly adapted ironmongery.



Redundant retractable canopy supports fixed to face of fluted column.



Top of redundant retractable canopy supports.



Original shop signage / fascia runs full width of Shop and adjacent residential frontage. Retractable canopy extends to the width of the shop fraontage and includes the recessed entrance to the residential unit.