

DETAILS OF PROPOSED WORKS

Side – North Facing Elevation



→ repoint chimney & (lime)
→ repoint walls where needed
(lime)

→ replace subframe window
with like for like
timber