

# **SCHEDULE OF COMPLETED REPAIRS**

**REPAIR ADDRESS: 90 HAYES LANE** 

**BECKENHAM** 


KENT BR3 6SP

**CONTENTS:** SITE LAYOUT

CCTV SURVEY DETAILS REPAIR SUMMARY RECOMMENDATIONS

QUOTATION PHOTOGRAPHS

**GUARANTEE OF REPAIRS** 



Client: 360GlobalNet

Regus House Herald Way

Pegasus Business Park

**Castle Donington** 

**DE74 2TZ** 

**Insured:** Mrs Caroline Millard **Reference:** DLG-SN-22-004722

1st Site Visit:12-Dec-222nd Site Visit:10-May-231st Report Date:13-Mar-232nd Report Date:16-May-23

Repair Commenced: 24-Apr-23 Completion Report Date: 28-Apr-23

The Drainage Repair Company Ltd | Office 6 | Unit 14/4 Station Road | Coleshill | Birmingham | B46 1HT

Telephone: 01530 272 349 Email: info@thedrainagerepaircompany.com

Registered in England & Wales Number: 08570351 | Registered Office: Bourne House, 475 Godstone Road, Whyteleafe, Surrey, CR3 0BL



SITE LAYOUT Site Crew: TLR/SD Date: 24-Apr-23 Boundary Run 3 Run 6 I/C1 I/C2 Run 4 Run 1 Run 5 Run 2 1/C3 Run 1 ORWP1 FWG1 KFWG2 Run 7 ORWDP2 Run 8 Run 1 W/C 90 Hayes Lane **Utility Room** RWG1 **FRONT** (This plan is not to be scaled and is provided to illustrate general layout only) General Comments: Note: Runs shown in red have been adopted by the local water authority. Key: ☐ = Storm Gully ○ = Storm Pipe ☑ = Foul Gully = W/C or Soil Pipe = Inspection Chamber O = Rodding Eye → = Surveyed pipe indicating flow ----→ = Unsurveyed pipe = Exploratory Hole (hand dug pit and/or hand auger)  $-\cdot - \cdot = Boundary line$ 📜 = Area of damage = Hedges & Shrubs = Trees & bushes



Site Crew:	TLR/ SD					Date:	24-Apr-23
<u>RUN:</u> 1	Pipe Dia. (mm):	100	System:	Foul Water	Made of:	Lined Cl	ay
From:	I/C4		Inv (m):	Upstream	To: W/C		Inv (m):
Metres		Faul	ts / Defects		Rer	marks	
0.00					IC4		
0.00					Line Left		
0.38					Material Change to VC		
0.91	No Visible Defect	ts			WC		
					End of survey		

<u>RUN:</u> 7	Pipe Dia. (mm): 100	System:	Foul Water	Made of: Lined Clay	
From:	I/C4	Inv (m):	Upstream	To: FWG2	Inv (m):
Metres	Fa	ults / Defects		R	emarks
0.00				IC4	
0.11	No Visible Defects			FWG2	
				End of survey	

<u>RUN:</u> 8	Pipe Dia. (mm):	75	System:	Foul Water	Made of:	Lined Clay
From:	I/C4		Inv (m):	Upstream	To: RWDP2	Inv (m):
Metres		F	aults / Defects		Rei	marks
0.00					IC4	
0.27					Line Up	
0.30	Crack on restben	d				
					End of survey	

Defects shown in RED relate to runs adopted by the Local Water Authority



### **EXECUTIVE SUMMARY**

**Brief:** The Drainage Repair Company Ltd were commissioned to undertake

a CCTV survey / inspection of the drainage at the property.

**Specific Area of Interest:** Accessible drainage at the property.

System Access: IC4 Upstream

Visual Survey: N/A

Water Pressure Test: No

### **SUMMARY OF FINDINGS**

**Defects requiring repair:** Yes

Is any damaged section shared: No

No. of properties sharing: N/A

Age of property / system: Unknown

Cause of damage: N/A

# **GENERAL SUMMARY**

The results of the CCTV / inspection survey to the underground drainage system at the above address are as follows:

#### IC4:

We attended site with IC4 now exposed and completed high pressure water Jetting and a CCTV survey to all the laterals within the chamber.



### **GENERAL SUMMARY**

The results of the CCTV / inspection survey to the underground drainage system at the above address are as follows:

### Run 1 - Foul - Private:

We completed high pressure water Jetting and installed  $1m \times 100mm$  patch liner to repair the run which goes upstream to the WC

### Run 7 - Foul - Storm:

The CCTV survey confirmed no defects within the run.

#### Run 8 - Foul - Private:

The CCTV survey confirmed cracking on the restbend to the RWDP which is 75mm

### **RECOMMENDATIONS**

We would recommend returning the system to a watertight condition by repairing the defects as follows:

#### **Run 8:**

To complete an internal excavation upstream of IC4 to remove amd replace the restbend to RWDP2. Backfill and reinstate leaving the area clean and tidy.

## **Enabling Required:**

- The area of concern will need to be cleared along with the removal of the carpet tiles.
- A carpenter will need to attend site to lift the wooden flooring, the joists and the joist supports

#### **QUOTATION**

### Run 8:

- To complete an internal excavation upstream of IC4 to remove and replace the restbend to RWDP2 which is 75mm pipework
- Backfill excavation
- Reinstate surface
- Remove excavated spoil from site


Total ex.VAT	£800.00
VAT	£160.00
Total inc.VAT	£960.00

£800.00	Grand Total - All Works ex.VAT
£160.00	VAT
£960.00	Grand Total - All Works inc.VAT













### 2.0 GUARANTEE OF REPAIRS

The terms and conditions of this guarantee shall apply to the provision of guarantee service, by **The Drainage Repair Company Ltd** 

#### 1. Guarantee Period

- 1.1 The Guarantee Period applicable to The Drainage Repair Company Ltd shall be:
  - i) Manufacturers Guarantee for various materials used.
  - ii) Drainage Repair 12 months from date of installation.
  - iii) Drainage Unblock 1 month from date of initial clearance, assuming the pipework to be in an
    - otherwise serviceable condition.
- 1.2 The above Manufacturers Guarantee refers to the time period whereby the products will perform for the duration of its reasonable life expectancy of that product, provided that it has been used solely for its normal purpose and used and maintained in accordance with standard operating/building or practice.
- 1.3. After replacement or repair of the Product, the guarantee for the new or repaired Product shall be valid only for the unexpired period of the original Guarantee Period.

### 2. Application Terms

- 2.1 The Product shall have been used solely for its normal purpose and used and maintained in accordance with standard operating/building instructions or practice.
- 2.2 The Guarantee shall not apply to malfunction or damage resulting from accidents, product misuse, improper use, abuse, neglect or negligence by the homeowner or anybody else.

Product installed, repaired, adjusted, rebuilt, modified, changed or converted by The Drainage Repair Company Ltd have been done so in accordance with the relevant British Standards pertaining at the time of installation.

### 3. Exclusions

The following are expressly excluded from this guarantee:

- 3.1 Maintenance services.
- 3.2 Consequential damages resulting from any defect in the product.
- 3.3 Blockages
- 3.4 Accidental damage including root ingress.

Should any problems be experienced with The Drainage Repair Company Ltd's service, please phone: **01530 272 349** 

This guarantee applies to works undertaken at the named property and remains valid should the property be sold within the lifetime of the guarantee. Please keep this Standard Guarantee Report with your invoice, as it will be needed when claiming service in terms of this guarantee.