



North Tyneside Council

**PLANNING****Regeneration and Economic Development**

North Tyneside Council, Quadrant, The Silverlink North,

North Tyneside, NE27 0BY

Tel: (0191) 643 2310

Email: [development.control@northtyneside.gov.uk](mailto:development.control@northtyneside.gov.uk)Web: [www.northtyneside.gov.uk](http://www.northtyneside.gov.uk)**Summary of Amended Application****Please Note**

It is always advisable to check the progress of your application with the Local Planning Authority to ensure that an amendment will be accepted by them.

Proposal Name

dormer window repair

Reference

PP-12791531

Version Number

2

Submission Date

Thursday, February 15, 2024

**Amendments to the Application Form****Declaration (Standard) - Declaration Date**

Previous Answers:

08/02/2024

Updated Answers:

15/02/2024

**Declaration (Standard) - Amendments Summary**

Previous Answers:

Updated Answers:

added scale drawing and further detailed photos. Also boundary amended

## Amendments to the Fee Calculation

No amendments made

## Amendments to the Location Plan

### Polygon / Site Boundary

Has the polygon / site boundary changed?

True

## Amendments to the Supporting Documents - Added

### Supporting Documents Added

Document Name	The location plan
Document Description	
Submission Date	Thursday, February 15, 2024
File Name	
Submission Method	System generated
File Type	
File Size (bytes)	

Document Name	Detail Drawing
Document Description	scale drawings of repair work. Frontage
Submission Date	Thursday, February 15, 2024
File Name	Front elevation.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	693353

Document Name	Detail Drawing
Document Description	scale drawings of repair work. Side view
Submission Date	Thursday, February 15, 2024
File Name	side elevation with measurements.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	204659

Document Name	Detail Drawing
Document Description	scale drawings of repair work. with materials, Side view
Submission Date	Thursday, February 15, 2024
File Name	side projection with materials.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	231392

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	Inside dormer.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	113619

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside east with 2ndary double glazing and opaque glass Close up.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	520448

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside east with 2ndary double glazing.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	390939

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside lower sash close up showing rotting frame.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	454446

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside sash close up showing catch loose cos of rotting wood.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	403805

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside sash.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	137546

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside upper sash close up showing lower corner rotten amnd come apart.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	435743

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside upper sash close up showing upper corner coming apart.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	397275



Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside west showing cracked panes and secondary double glazing Close up.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	439299

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	inside west showing cracked panes and secondary double glazing.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	343085

Document Name	Elevation (Front) - Existing
Document Description	Current state of window
Submission Date	Thursday, February 15, 2024
File Name	outside close up.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	184003

Document Name	Elevation (Front) - Existing
Document Description	current front
Submission Date	Thursday, February 15, 2024
File Name	outside front projection contrast.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	286905

Document Name	Elevation (Front) - Existing
Document Description	current front
Submission Date	Thursday, February 15, 2024
File Name	outside front projection.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	183675

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	outside sash east side showing rotten frame and missing timber overhang.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	325094

Document Name	Additional plans
Document Description	photos to show current damage and current secondary double glazing
Submission Date	Thursday, February 15, 2024
File Name	outside sash showing rotting wood.JPG
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	319617

Document Name	Elevation (Front) - Existing
Document Description	current
Submission Date	Thursday, February 15, 2024
File Name	outside side projection east contrast.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	177542

Document Name	Elevation (Front) - Existing
Document Description	current
Submission Date	Thursday, February 15, 2024
File Name	outside side projection east.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	229134

## Amendments to the Supporting Documents - Updated

### Supporting Documents Updated

No supporting documents updated

# Amendments to the Supporting Documents - Deleted

## Supporting Documents Deleted

Document Name	Elevation (Front) - Existing
Document Description	dishevelled current dormer
Submission Date	Thursday, February 15, 2024
File Name	dormer 2.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	197831

Document Name	Elevation (Front) - Proposed
Document Description	like for like replacement plan
Submission Date	Thursday, February 15, 2024
File Name	Dormer diagram.jpg
Submission Method	Uploaded to storage
File Type	image/jpeg
File Size (bytes)	24560