

Photo 2: POS and marketing suite (POS1 in wild flower meadow to the left of photo and POS2 in centre of lawn to the right of photo)






Photo 3: Plot 1 Hand Pit





Photo 4: Plot 1





Photo 5: Plot 1 subsoil





Photo 6: Plot 2





Photo 7: Plot 3





Photo 8: POS1






Photo 9: POS1 arisings





Photo 10: POS2

# Appendix E - Additional Photographs





1- Google Earth Photograph, July 2021





Photos below: Non-Hazardous Waste Stockpile









Photos below: Hazardous Waste Stockpile







### 06/05/21 Remediation Works in centre of site













Above: Windrow Turning in South-West of the Site





19/05/2021 General Works in North and North-east

















### 02/06/2021 General Works Across Site

















**Dust Suppression and Odour Suppression** 





14/06/2021 North-west corner excavations and Post Cottage Demolition









### 15/06/2021 General Works Across the Site















09/06/2021 General Works











02/07/2021 General Works in Central Part of the site















05/07/2021 Works in Central Part of the Site







#### 07/07/2021











08/07/2021









21/07/2021













## 11/08/2021 Cottage Validation Trial Pits







### 15/09/2021









In-situ Groundwater Treatment in North-East of the site





13/10/2021 Infrastructure Works

