





Window 01.  
Living Room

Window 02.  
Living Room



Ironmongery is non-existent in areas and requires to be installed. Gaps to window frame and sash are allowing draughts to enter property.

Defective cill requires to be replaced/ repaired.



Defective sections of timbers require to be replaced.



Window 03. Bedroom 01



Defective rope cords do not allow for ease of opening for the user



Window sash out of alignment causing weak contact points at mid transom, top sash and bottom sash, allowing major draughts to enter the property. Has been retrofitted with inadequate face fixed brushes.



Defective easy clean battens and ironmongery requires replacement.

