

Structural Defect Report - List below any visible External/Internal defects

Kitchen S.D.G will sit on sink edge  
Cables in Lounge will need to be notched into cill on LH side & butted upto BT box on RH side

PLEASE NOTE: It is not always possible to identify if lintels are present when the existing windows/doors are in situ. If at point of install it is found that the structure is unsupported/compromised then it may be necessary for lintels to be installed. Should this be the case then additional costs will apply to the customer in order to make the aperture structurally sound.

General Notes / Special Requirements

install S.D.G to existing windows finishing with white primers inside scribed into walls  
customer to remove files in kitchen


Variation Of Contract

Designs changed from Contract	Yes	<input checked="" type="radio"/> No
Plus/Minus costs apply and have been agreed with the customer (As shown below)	Yes	No

NOTE: If agreement on costs is not reached, this order will be referred to Business Approvals for assessment

Reason for Variation (include sketch to show design changes from and to)

S.D.G can be seen from outside



Current Gross Contract Price	Gross Adjustment - Plus/Minus	New Gross Contract Price
Customer/Authorised Signature:		Date:
Surveyor's Signature:		Date: 1.12.23