Coniston

41 – 43 Hays Mew's, Roof Slate Condition Report – 05.01.2024, Rev. 1.0

Author Heather Jackson-Wall

NOTES

- o Condition recorded on site at 41 43 Hays Mews, London, W1J 5QA.
- O Slates selected at random from those removed from roofs 2, 3, 4, 5 & 6.
- o The below is assumed indicative of condition across above noted roofs, but not confirmed conclusive.
- Dimensions noted in millimetre.
- Width & length recorded ≤ dimension.
- o Thickness recorded using RS PRO RS Pro Electronic Micrometer IP40 DIN 863

Slate #	Width	Length	Thickness	No. Holes	Note	Origin	Image
1	237mm	450mm	4.59mm		Significant damage, split	Wales (Penrhyn)	

	306mm 294mm 3.17mm 2 Delamination to rear Delamination to rear	
--	---	--

3	312mm	464mm	3.7mm	2	Acceptable	Wales (Penrhyn)	
							[10] 10 10 10 10 10 10 10 10 10 10 10 10 10
							And the first of t
							AND

	4	309mm	449mm	4.73mm	4	Fracturing around holes	Wales (Penrhyn)	
--	---	-------	-------	--------	---	-------------------------	-----------------	--

5	308mm	457mm	4.62mm	4	Fracturing around holes	Wales (Penrhyn)	

6	311mm	466mm	4.49mm	4	Significant damage, split	Wales (Penrhyn)	

7	307mm	458mm	5.95mm	4	Chamfered corner, delamination and chalking	Wales (Penrhyn)	
---	-------	-------	--------	---	---	-----------------	--

8	254mm	509mm	4.19mm	2	Delamination around holes on rear	Wales (Penrhyn)	

9	276mm	310mm	2.2 - 5.6mm	4	Delamination around holes & at one end	Wales (Penrhyn)	
							The state of the s

10	311mm	277mm	6.8mm	2	Delamination around holes	Wales (Penrhyn)	
----	-------	-------	-------	---	---------------------------	-----------------	--