



The west brick gable currently bows outwards, past the roof boundary line at second floor level. This needs to be rectified.

EXISTING WEST ELEVATION
Scale: 1:100

Covered UPVC basement window to be replaced with a more appropriate timber window well.



Scale: 1:100