



Roof slopes 5 & 8 labeled above are the two main inward facing roof slopes, which following initial investigation appear to have been re-roofed in the past. These roof slopes have a thinner Spanish slate, and this is the area that is likely to require replacements as the thinner slates will be more fragile and likely to be damaged during the works. The other areas of the roof are a thicker and more robust slate which will be easier to reclaim and reuse.

**Proposed roof plan**

**Project:** Proposed alterations & refurbishment at Old Rectory, Tostock  
**Client:** Mr & Mrs Bowyer

**Drwg:** 23 1860 17 **Revision:** -  
**Date:** Feb 2024 **Scale:** 1:100 @A2

The Studio  
 Drinkstone Office Park  
 Kempson Way  
 Bury St Edmunds  
 Suffolk IP32 7AR  
 Tel: 01284 756166  
 Email: rp@reespryer.co.uk



Do not scale from drawings. Any discrepancies or omissions to be reported to the Architects. Copyright remains solely with the Architects unless express permission is granted otherwise. Whilst every effort has been made to design out all risks associated with this project some may still exist - if you do not fully understand the risks involved refer to the project health and safety plan or consult your manager, health and safety advisor or a member of the design team before proceeding information based on Survey Solutions data