



Thatch failing and allowing water into fabric



Floor joists coming away from wall



Cobb damage due to water ingress



Stable roofs have failed and are falling inwards



Temporary propping



Ceiling cracks and plaster falling in



Due to failed thatch, water ingress has caused damage to cobb wall and timbers



Cracks in brickwork on Bothy building



Cracks in oven/fireplace feature



Ceiling cracks and plaster falling in