

| 2

Photo 4

Looking Southwest towards the Greenhouses / proposed site for PV Panels from the entry point into the side garden.



Photo 3

Looking North towards Hamstall Hall in the back part of the 'side garden'. Dense planting separates the front / back parts of this walled garden. To the right we see a remainders of the original C16 Hamstall Hall. This was the described as the "gabled bay facing south" and it is the most aesthetically pleasing (remaining) aspect of the Hamstall Hall site.




Photo 2

Within the rear garden at Hamstall Hall. Looking towards a surviving Tower from the original C16 Hamstall Hall. This grass area would have formerly been internal floor space within the Hall making it likely to hold archaeological remains and thus, an unsuitable site for the PV proposals. (Backdrop St. Michael's Church).



Photo 1

In the modern day this driveway leads to the principal elevation of Hamstall Hall as we see it (C21) from Blithbury Road. This is thought to date from mid C19 early C20 based on Historic Maps.





| 3

| 5



Photo 5

In the 'Walled Garden' alongside Blithbury Road. In the photo we can see some modern additions, some raised planting beds, a timber 'potting shed' and two greenhouses. The proposals are to be located alongside the greenhouses in an area which receives good levels of sunlight. (Photo taken 21-09-23 at 10:49AM).



Photo 6

Closer view of 'Photo 5'. In the distance beyond the dense vegetation which separated the 'front' and 'back' areas of the 'side garden' we can see the Spire of St. Michael's Church. This photo is taken in the exact site of the proposed PV Panels. Analysis of the site has found this to be the most suitable location for these modern additions.



Photo 7

The 'Walls' separating the 'side garden' from Blithbury Road. These are historic red brick walls which exhibit mixed brick bonding. There is some evidence of Flemish Bond, some evidence of 'English Bond / English Garden Wall Bond, some Stretcher Bond' all capped with a decorative brick coping.



Photo 8

The 'Garden Walls' as described in 'Photo 7'. These are Grade II Listed and have evidential, historic and aesthetic significance. Condition is fair given its age, although some aspects are poor and repairs have been carried out in multiple phases.

Notes

Copyright b3architecturaldesign 2020. Reproduction not permitted without prior written consent.

Only figured dimensions to be referenced from these drawings, if in doubt please ask for further dimensions. All figures to be checked on site prior to commencement. This drawing is intended for planning or building regulations use only, b3architecturaldesign and the author have not prepared this drawing for construction purposes. It is indicative for specification purposes only. Deviation from this drawing will not be permitted without prior written consent.

The recipient of this drawing shall make themselves aware of any obligations under CDM 2015 (Construction Design and Management). b3 architectural design have considered all foreseeable design risks involved with the architectural elements; however are not the 'Principle Designer' role.

The recipient of this drawing shall make themselves aware of any obligations under the Party Wall Act 1996. The information on this drawing is for indicative purposes and does not overrule any requirement within the act.

All drainage information is indicative and must be confirmed on site prior to commencement.






Photo 9 From the back part of the 'side garden'. In this photo we can see the original C16 bay of Hamstall Hall and the C14 Church Spire in the background. We can also see the dense vegetation which separates St. Michael's Church from the application site.



Photo 10 The Principal Elevation of St. Michael's Church (Southeast Elevation). This is well shielded by dense vegetation between the application site.

