

Photographs 1: Kitchen window to be replaced


Kitchen Window
(rear of property)



Zoom view showing style
and deterioration



Internal view
showing style



Internal view
showing rot and
leakage

