



Existing Doors formed from plywood and in poor condition. Doors are not original (ply), so a repair would not be ideal. Door is rotten. Replace with solid timber doors and new glazing (double to match existing), painted black. New door handle and locks. New ironmongery.



St Martin Church, Belper, England	EXISTING SOUTH DOOR
Mar 23	
Ref - 22CHURCHINTERIORS07	