




Existing Doors formed from plywood and in poor condition. Doors are not original (ply), so a repair would not be ideal. Replace with solid timber doors and new glazing (double to match existing), painted black. New door handle and locks. New black ironmongery to match existing.



PROPOSED ENTRANCE - NORTH ELEVATION
SCALE 1:50 @ A3



St Martin Church	PROPOSED NORTH DOOR
Mar 23	
Ref - 22CHURCHRENEWALS06	