



**MAPLEBECK**  
TREE CARE

## Professional Arboricultural Care Management Report

16th April 2024

A name you can trust!

Maplebeck Tree Care Ltd

Clay Barn, Maplebeck, Newark, Nottinghamshire NG22 0BS

Tel: 01636 636 763



Mob: 07837 048542

Web: [www.maplebecktreecare.co.uk](http://www.maplebecktreecare.co.uk)

Email: [info@maplebecktreecare.co.uk](mailto:info@maplebecktreecare.co.uk)

Vat Registration Number 270 7572 91

JOB REF No. 4137




### Site Address:

Woodpecker Cottage, High St Girton NG23  
7JA

### Client Address:

Carol Pykett  
Woodpecker Cottage, High St Girton NG23  
7JA



Reference G=Group H=Hedge T=Tree	Age & Species	Height (m)	Crown Ht (m)	Diameter (cm)	Crown spread (m)	Notes  All measurements are for our guidance purposes only	Recommendations		Life expectancy
							Priority		
							Inspect Frequency (yrs)		
T=Tree	T1 Mature Cupressus Species	12	2	48	6	<p>If quote accepted conservation area application will be me by ourselves.</p> 	<p>Compression union at 2m in height between co dominant stems. The union has partially failed with a lateral crack formed on the garden side of the stem. If one of the stems failed it would land on the main road through the village and fully block it. The client has strapped the stems together. Requesting permission to remove the tree leaving a stump as a feature for the clients. High N/A</p>		
T=Tree	T1	-	-	-	-	<p>2 options provided.</p> 	<p>1st. Remove to ground level stacking the debris in the garden and sawing the logs into 10 inch rings.</p>		
T=Tree	T1	-	-	-	-	<p>W3W's of property = spring.hence.mush</p> 	<p>2nd. Remove all arisings below 8 inch diameter from site stacking the remaining logs in situ in 10inch rings.</p>		



Map/diagram where appropriate

