Materials:

1. Flint facing
2. Red facing brick
3. Timber Cladding
4. Red plain tiles
5. Timber windows/ doors
6. Timber fascia and soffits
7. Black plastic rain water goods

Conservation rooflights of similar appearance as existing

Plain tiles of similar appearance as existing

Facing brick of similar appearance as existing

Timber windows of similar appearance as existing with obscure glazing

Facing brick of similar appearance as existing

New 6ft fence panels
Or
Replacement planting of Yew as recommended by Arboriculturalist

Timber windows of similar appearance as existing

Timber doors of similar appearance as existing

Timber french doors of similar appearance as existing

PROPOSED SIDE (WEST) ELEVATION

Conservation rooflights of similar appearance as existing

PROPOSED SIDE (EAST) ELEVATION - GARAGE

Timber windows of similar appearance as existing

Plain tiles of similar appearance as existing

Plain tiles of similar appearance as existing

New 6ft fence panels
Or
Replacement planting of Yew as recommended by Arboriculturalist

Facing brick of similar appearance as existing

Timber windows of similar appearance as existing

Facing brick of similar appearance as existing

PROPOSED SECTION AA

PROPOSED SECTION BB

0   1   2   4m