BUILDING BAY COLLAPSED

new slates on battens on breather felt on t+g boarding on rafters

existing timber trusses, common rafters, ties and purlins inspected and any defective members replaced in oak + same sections as existing

T7 T6 T5 T4 T3 T2 T1

new - Nat stone both sides on conc block wall

(dismantle to build wall)

barge boards

RL RL RL

new oak wallplate

Boarding on breather felt on Timber frame + boarding int

Powder coated ali. doors + side lights Duo 1

2100

new boarding on stud wall + ply lag stone side

frame inspected + repaired

new patio

new stone pavors on mortar on sand blinded h/core

wood beams

inspect brick wall to u/s timber frame (may need new brick wall + conc strip founds under)

natural stone conc. founds

SECTION 'B'

new conc founds

T7 T6 T5 T4 T3 T2 T1

new river edge slates on battens on breather felt on t+g boarding on rafters

new black powder coated ali gutters + downpipes

rebuild nat stone wall

new boarding on breathes felt on frame + boarding int.

Received

21 FEB 2024

Council Development Services

new patio

7 6 5 4 3 2 new timber door and frame 1

SOUTH ELEVATION

Repair exist oak posts + staddle stones ① to ⑦ oak beams over retained.

* oak bracing feature retained

Revision

B West end bay collapsed new gable end wall built in new location } Feb 2024

TYTHE FARM. GOPSHILL LANE. GRETTON. GLOS. GL54 5ET

BUILDING 'B' SECTION/ELEVATION AS PROPOSED 1:50

21:1935:19B OCTOBER 2023

DENNIS L RAYTON TEL 01242 620818