


**NOTE:** exact type of stitching to be agreed on site with CA. Where threaded dowels used they must be stainless and should bed into the stone at least 200mm either side of crack. In some cases a full stone indent may be required





201 The White Studios Templeton Business Centre Templeton Street, Glasgow G40 1DA Tel 0141-551 8383 Fax 0141-554 7884 e-mail: info@johngilbert.co.uk www.johngilbert.co.uk

Rev	Date	Alteration			
Α	24/11/20	Rod set into slot & indented omitted			
Job N	lo		Drawn by		Size
03749			JG		A3
Date 29/9/20			Scale NTS		
29/9/20			INIC	,	
WOODSTOCK CHURCH					
TITLE INDENTING, FIXING, STITCHING					
Drg No [21]23				Rev A	