




04 - Eaves detail



05 - Ridge detail




06 - Verge detail



Drawing No. 161/106

Poulsom Architectural Design Services



* Before the start of work all site measurements, angles & levels must be checked by the contractor in the event of any inaccuracies on this drawing no liability or responsibility will be accepted once work has started.

* These drawings are for planning & building regulations approval only.

* Any works carried out prior to the necessary approvals being granted are carried

* These drawings are copyright and their use or reproduction without the written permission of Poulsom Architectural Design Services is prohibited.

* Party Wall - where work involves alterations to a party wall or works close to a boundary, it is the owners responsibility to comply with the necessary notices etc. required by the Party Wall Act. 1996. Notices to be served at least two months before work commences.

* Only the materials on this drawing are to be used. Any substitutions must be of a similar quality & standard as that stated. All materials are to be used in accordance with manufactures instructions unless otherwise directed.

* All construction projects large and small are subject to the CDM Regulations (2015). If the development will be for a domestic Client or less than 30 days in duration then the responsibility for Health and Safety is then passed onto the Main Contractor. In all cases the Client may devolve the responsibility to a CDM Planning Supervisor, who will act on the Clients behalf. Please refer to Panning Supervisor for * Before starting work you need to check if any asbestos is present, in Commercial properties there should be a plan/register - <u>Ask to see it</u>. You need to check that the plan covers the area of the building that you will be working in and if you are doing refurbishment work that it includes a survey that tells you what types of asbestos is present and its condition. If there is no Register or survey or the report is not clear - <u>Do not start work</u>.