



Fault in lead gutter lining allows water to pass beneath gutter and to pass between stone facing and brick wall.

Location of sample clean #1.

SOMERSET HOUSE ~ NORTH FACADE
 SKETCH SECTION THROUGH PARAPET