




Bedroom




Bedroom




Bedroom




Master bedroom




Ensuite




Hallway




Lounge




Dining room




Snug




Snug



Dining room



Kitchen



Lounge

Existing windows & doors

- Some of the windows doesn't have any historical value as we believe it is 1980s replacement
- Current various windows design devalues historical building
- The majority of front windows rotten, moulded, and don't do their functions, which creates ventilation, fire escape and health and safety issues, and a beyond of repair.
- The window & door frames bowed and created drafts and CO2 pollution.

Schnauber
 Address: 44 Mill Rd, Cambridge
 CB1 2AS
 Phone: 01223 929293
 email: info@schnauber.co.uk
 www.schnauber.co.uk

