

CONTEXT

- 1. EXISTING SIDE ENTRANCE TO ACCESS PLAYGROUP IS NOT INVITING.
- 2. OIL TANK STORAGE AREA IS NOT USED AND TAKING UP VALUABLE SPACE IN THE GARDEN THAT CAN BE REPURPOSED.
- 3. NO PROTECTION FROM THE WEATHER DURING DROP OFF.
- 4. ADDITIONAL MEETING SPACE FOR TOLL CENTRE REQUIRED TO ALLOW ACTIVITIES TO TAKE PLACE DURING INCEASED PLAYGROUP HOURS.
- 5. AREA REQUIRED TO ALLOW PARENTS / CARERS TO HAVE MEETINGS ETC.

O1_SITE PLAN



Olient			
THE TOLL COMMUN	NITY CENTRE		
lob	Description	Scale	Date
THE TOLL COMMUNITY	SITE PLAN	NTS@A3	AUG 20
CENTRE	ANALYSIS		
EAST TOLL PARK	Drawing Number	Revision	
KIRKCALDY RD	940_(P)_004	_	
BURNTISLAND	340_(i)_004		
KY3 9HA			



- e. info@signalarchitects.com t. 01383 860941
- w. www.signalarchitects.com