

Existing masonry vaulted ceiling exposed, repointed and made good. Fire integrity of existing floor structure to be determined by specialist engineer. Any additional fire protection measures to be agreed with Heritage England and Local Planning Authority	(

Plasterboard	suspended	cei