



Appendix 2 Site Photographs





Plate 1: Overview of eastern field, taken from near TP324 looking east.



Plate 2: Overview of eastern field, taken from near TP213 looking east.





Plate 3: Overview of earthworks and existing site compound in the northern field.



Plate 4: Overview of earthworks in the eastern boundary of northern field.





Plate 5: Overview of earthworks in the northern field.



Plate 6: Overview of earthworks in the northern field.





Plate 7: Overview of southern field, taken from near TP348 looking south.



Plate 8: Overview of southern field, taken from near TP348 looking east.





Plate 9: Overview of bund located in the southern field, taken near TP332 looking west.



Plate 10: View of southern field, taken from near TP340 looking southwest.





Plate 11: View of flooded area in the northwest area of the south field.



Plate 12: Overview of old road with flooding at either side, taken from TP363 looking north.





Plate 13: Overview of western field, taken from near TP375 looking west.



Plate 14: Overview of western field, taken from near TP381, looking north.





Plate 15: Overview of fenced off area of Japanese Knotweed, undertreatment by ERS



Plate 16: Overview of western field, taken from TP396 looking south west.