

- Windows to be replaced with new double glazed timber sash windows to match existing 1
- 2 New 'conservation style' rooflights

Notes: Replacement of faulty rainwater goods as per existing where necessary

Brickwork to be repaired and repointed as per existing where required

				Astrain Scheldt				
					info@astrainscheldt.com	www.astrainscheldt.com		m
				Project	Client	Scale @A3 First Issued		sued
				66 Osborne Road, Forest Gate, London, E7 0PH	Ms Hong Nguyen & Mr Stefan Ubovic	1:50 04.06.21		.21
				Drawing Title	Status	Drawing No.		Rev.
2M	3M	4M	5M	Proposed North (Front) Elevation	Planning	2162-210		А