

2 New 'conservation style' rooflights

1

---- Site Boundary

Notes: Replacement of faulty rainwater goods as per existing where necessary

Brickwork to be repaired and repointed as per existing where required

1M

info@astrainscheldt.com Scale @A3 First Issued Ms Hong Nguyen & Mr Stefan Ubovic 66 Osborne Road, Forest Gate, London, E7 0PH 04.06.21 1:50 Drawing No. 2M 3M 4M 5M Proposed First Floor Plan Planning 2162-201