

- Windows to be replaced with new double glazed timber sash windows to match existing
- 2 New 'conservation style' rooflights

Notes:

---- Site Boundary

Replacement of faulty rainwater goods as per existing where necessary

Brickwork to be repaired and repointed as per existing where required

0 1M 2M 3M 4M 5M

Astrain Scheldt				
	info@astrainscheldt.com	www.astrainscheldt.com		m
Project	Client	Scale @A3	First Issued	
66 Osborne Road, Forest Gate, London, E7 0PH	Ms Hong Nguyen & Mr Stefan Ubovic	1:50	04.06.21	
Drawing Title	Status	Drawing No.	wing No. Re	
Proposed Section AA	Planning	2162-220		Α