



T3 Large Sycamore in decline with a considerable lean towards outbuildings.



T3 Large Sycamore
from the rear of
outbuildings showing
severity of lean.



T1 Ash showing signs of dieback and a lean towards a neighbours house.



T2 Sycamore proposed removal due to lean and a poor example of low amenity value