

abutments with gable copings.

round downpipes.

of internal cross walls.

MASONRY

RAINWATER GUTTERS & DOWNPIPES

Black powder coated round section gutters on rise and fall brackets and

Dismantle and rebuild sections of external masonry above window

Carry out Helifix crack repairs to south gable end wall and at abutment

Fill in two window openings on west elevation with masonry in materials

opening in northwest corner and to corner of south east gable.

coursed to match existing. New masonry recessed 50mm.

Block vent on south gable with stone retaining recess on outside.

Rake out & re-point external masonry with lime mortar flush pointed.

masonry.

Retain wooden troughs in Store 1.

system and /or soakaway.

Provide below ground storm water drainage connected into existing

Proposed Plan,
Elevations & Section

CMPS
COLIN MOORE architect

Lodge Barn Lindsey Close Woodnewton Peterborough PE8 5EW T: 01780 470636 E: cmpsarchitect@gmail.com

scale 1:100 1:50 @ A1 drawing no. 20.05/11